

Wildcat Farms, LLC
Hancock County
May 12, 2011
(IEPA Star M. Fowler)



Photograph #1. Mortality compost area, thermometer can be seen.



Photograph #2. Mortality compost area with bones exposed.

Wildcat Farms, LLC
Hancock County
May 12, 2011



Photograph #3. Vegiative Environmental Buffer, both rows of trees can be seen. View is east.



Photograph #4. Upright PVC clean out pipe, surrounded by markers.

Wildcat Farms, LLC
Hancock County
May 12, 2011



Photograph #5. Beinging of unnamed stream on-site enters Wildcat Creek. View is northeast.



Photograph #6. Pump Station that pumps manure into both slurry tanks.

Wildcat Farms, LLC
Hancock County
May 12, 2011



Photograph #7. Inside Pump Station, manual lever changes flow into respective slurry tank.



Photograph #8. Two valve system one for release and one for agitation.

Wildcat Farms, LLC
Hancock County
May 12, 2011



Photograph #9. Side wall of slurry tank.



Photograph # 10. Inside the East slurry tank.

Wildcat Farms, LLC
Hancock County
May 12, 2011



Photograph # 11. Inside the West slurry tank.



Photograph #12. The West slurry tank, liquid level depth marker broken.

Wildcat Farms, LLC
Hancock County
May 12, 2011



Photograph #13. Generator Unit 668163 located on-site.



Photograph #14. Inside Generator unit.

Wildcat Farms, LLC
Hancock County
May 12, 2011



Photograph #15. Sample B-1 located north of gravel lane.



Photograph #16. Downstream of Sample B-1 north side of gravel lane.

Wildcat Farms, LLC
Hancock County
May 12, 2011



Photograph #17. Downstream of Sample B south of gravel lane. View is north.



Photograph #18. Sample B located north of slurry tanks.